

HyperTerminal Instructions

1. In windows 2000/XP go to Start
2. Select Run
3. Type Hypertrm and select OK
4. Enter a name for your session and select an Icon
5. Select the COM port you are connected to
6. Verify settings at:
 - Bits Per Second:** 9600
 - Data Bits:** 8
 - Parity:** None
 - Stop Bits:** 1
 - Flow Control:** hardware
7. A menu should now display on the HyperTerminal window.

There are other terminal emulation programs available. Tera Term is available for free at <http://hp.vector.co.jp/authors/VA002416/tterm23.zip>

Any questions or concerns arising from this procedure should be directed to the BayTech support team at:

support@baytech.net

Bay Technical Associates
200 North Second Street
Bay St. Louis, MS 39520
Domestic: 800.523.2702
International: 228.467.8231